

JC67 JC77	OMO Initiated OMO OMO	UC UC Research	Approval Approval UC	Vacant UC position Title MW Refresh	Description The alternate Federal-Non DOD DOI position is vacant. Active Op	23Apr18: The OMO was informed that Mr. Kenneth Hallett is no longer working for the BLM. 16Jan20: At the January 16 Executive Council meeting, Mr. Del Smith and ASAC Adam Pierce agreed to conduct a telephone call with the BLM to get an individual appointed. Perational Issues Status / Actions	Opened 23-Apr-18	Targeted Close Date 30-Dec-18
JC77 No.	Initiated OMO	Research	Approval	position	position is vacant. Active Op	working for the BLM. 16Jan20: At the January 16 Executive Council meeting, Mr. Del Smith and ASAC Adam Pierce agreed to conduct a telephone call with the BLM to get an individual appointed.		30-Dec-18
No.	ОМО							
	ОМО							
	ОМО				Description		Ononod	Targeted Close
)P05		OIT	UC	MW Refresh		Status / Actions	Opened	Date
					Outages caused by MW bouncing (Glenn Hwy to Richardson Hwy)	7Feb18: Funds were identified to replace this string of legacy MW last last year. Request to purchase was denied. 6Feb19: Funding for replacement is now in the procument process. 4Nov19: 55-hops of microwave has been procured and installation has begun at various sites throughout the system.	7-Feb-18	30-Dec-20
)P06	ОМО	JBER	UC	R1 North	Rectifier issue	11Mar19: One of the six rectifiers at the R1 North site has failed. 26Mar19: Per SSgt Paice, they are working to get quotes to get the battery banks and the rectifiers replaced.	11-Mar-19	30-Sep-19
)P07	ОМО	SOA	UC	Quantars	Replacement of SOA Quantars	12Mar19: The ALMR System cannot go beyond the 7.17 software platform until the SOA completes the replacement of all of its Quantars.	12-Mar-19	31-Dec-20
)P08	OMO	USARAK	UC	Black Rapids	Battery plant failed testing	3Apr19: The SOA tested the battery plant at Black Rapids and found some of the battery cells are dead. Battery plant needs replaced. 7Aug19: Mr. Williams stated Black Rapids was still being looked at; the site could see a power refresh and they expect to submit the projects through the Defense Logistics Agency and through the Department of Public Works, possibly as soon as next week.	3-Apr-19	31-Dec-19
)P10	ОМО	USARAK	UC	Donnelly Dome rectifiers	Rectifier issue	3Apr19: The rectifiers at Donnelly Dome need to be replaced. They are the same make as the ones at Birch Hill. No spares available and no one will work on them. 7Aug19: Mr. Williams stated Donnelly Dome needs a new DC power system; the site could see a power refresh and they expect to submit the projects through the Defense Logistics Agency and through the Department of Public Works, possibly as soon as next week.	3-Apr-19	31-Dec-19
)P12	OIT	Clear	UC	Clear	Microwave	3Apr19: The Clear microwave needs to be modernized	3-Apr-19	30-Jun-20
)P13	OIT	USARAK	UC	Birch Hill Master Site	UPS Side A failed	2Apr20: Power outage at the Birch Hill Master Site occurred on March 11 around 3:00am. The technicians found that UPS 01 failed and was not passing power to the equipment on the ALMR "A" side power. They put the UPS in bypass to restore power to the equipment and called the power contractor on base to get an emergency ticket opened. Currently UPS 01 is still in bypass, so it is running on AC and has no back up power.	2-Apr-20	31-Aug-20
						and the last worth		
IOTE					Issues CLOSED at	, or since, the last meeting		

NOTE: Yellow highlight indicates change since last meeting

20200402_May 6 UC IRLog.xlsx 4/30/2020